Work Orde Monday, July 19,								:		,	Page 1
Revision ID:	D3913-1			Accept				IIIII s	Setup Star		
	Rib 7/19/2010 7/23/2010	Start Qty: 3.00 Req'd Qty: 3.00			Cust Item 1 Customer:	ID:			, 510	P	
	Process Pla	n:	Date:	Tooling: SPC (Y/N):	-	ate:		ł	Run Sta Sto		
Sequence ID/ Work Center ID		Operation Description		Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Rev A	ision Nbr								·	
100 Large Fab Large Fab		2- Drill h	pe as per dwg D3913 role as per dwg ***one side o e identification marks and del	,	07-20			3			
110 QC Quality Control		QC5- Inspect part com	npleteness to step on W/O	0.00	ه (۱۹۸۱ه			-3			
120	•	Identify as per dwg &	Stock Location: WA	0.00 SF 0.00 (O~	107 120 110			,3			

Packaging

Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								\$	
Part No	:	PAR #:	Fault Cat	tegory:	_ NCR: Ye	s No D	QA:	Date:	
	R	esolution:	Dispositi	on:	_ QA: N/C	Closed: _		Date: _	
NCR:			WORK ORI	DER NON-CONFORMA	ANCE (NO	CR)			
DATE	CTED	Description of NC		Corrective Action Section		Veri	fication	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sig: Da	n&.∣ _{Se}	cton C	Chief Eng	QC Inspector
							·		
	<u> </u> ;						-		
						i.			
							1		

Work Ord Monday, July 1												Page 2
Item ID: Revision ID: Item Name: Start Date: Required Date	D3913-1 Rib 7/19/2010 : 7/23/2010	Start Qty: 3.00 Req'd Qty: 3.00		Accept	Cust Item I	I IIII III III			Setup	Start Stop		1818
Reference: Approvals:	Process Pl	an:	Date:	Tooling: SPC (Y/N):		te:		1	Run	Start Stop		
Sequence ID/ Work Center I 130 QC Quality Control	D	Operation Description QC21- Final Inspection -	Work Order Release	Set Up/ Run Hours 0.00	Tool ID	Tool#	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp

Dart Ae	rospace	e Lia								
W/O:			WO	RK ORDER CHA	NGES					
DATE	STEP	PRO	OCEDURE CHAI	IGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Categ	jory:	NC	R: Yes	No DQ	A:	Date: _	
	R	esolution:	Disposition	ı:	QA	: N/C Cld	osed:	ļ	Date: _	
NCR:			WORK ORDE	R NON-CONFO	RMANCE	(NCR)			
D.4.	0.750	Description of NC		Corrective Action	Section B		Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Descript Chief Eng	tion	Sign & Date		on C	Chief Eng	QC Inspector
									l L	
									ŀ	
					,					
		1	· · · · · · · · · · · · · · · · · · ·				1		1	

Picklist Print

Monday, July 19, 2010 8:51:03 AM

Work Order ID: 60674

Parent Item: D3913-1

Parent Item Name: Rib

Start Date: 7/19/2010

Required Date: 7/23/2010

Page 1

Start Qty: 3.00

Required Qty: 3.00

Comments:

IPP Rev:A new issue DD 10.03.19 verified by:EC add drill one side only DD 10.04.12 verified by:EC


IPP Rev:B

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304TS0.750W.049		Purchased	No			100	f	226.6300	=	25.26316			
304 SQ Tube .75x.75x.049										SAC)	10-0	57-20


Loc	ation	Loc Oty	Loc Code	
MA	T	40.83646794	ι	
	113763	0		
	114323	20.0582189		
	114677	14.34201		
	114835	6.436239		
MA	T017	3.68448E-05		
	114298	3.6845E-05		
WA		185.7935		
	114992	185 7935		25 3

Dart Aerospace Ltd W/O: WORK ORDER CHANGES DATE STEP PROCEDURE CHANGE B


DATE	STEP	PRO	PROCEDURE CHANGE By D					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					į					
Part No	:	PAR #:	Fault Cate	egory:	NCR: Ye	es N	o DQ	A:	_ Date: _	
	R	esolution:	Disposition	on:	QA: N/C	Clos	sed:		Date:	
NCR:		V	VORK ORD	ER NON-CONFORMA	NCE (N	CR)				
		Description of NC		Corrective Action Section			Verifi	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		n & ate		on C	Chief Eng	QC Inspector
	<u>.</u>									
	1									
									i	
									,	
	Ì									




W/O:			W	ORK ORDER CHAN	GES					
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						ļ				
Part No		PAR #:								
	Re	esolution:	Dispositi	on:	QA: N	I/C Clo	sed:		Date: _	
NCR:			WORK ORE	DER NON-CONFORM	MANCE (NCR)				
DATE	STEP	Description of NC			ection B		Verifi	ation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng)	Sign & Date		on C	Chief Eng	QC Inspector
										1
									. ,	



W/O:			W	ORK ORDER CHANG	ES				1:
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						, i ii i		Prod Mgr	
·				· · · · · · · · · · · · · · · · · · ·					
Part No		PAR #:	Fault Cate	egory:	_ NCR: Yes	No DQ	A:	_ Date: _	
	Res	solution:	Disposition	on:	_ QA: N/C Clo	osed:		Date: _	
NCR:		,	WORK ORE	ER NON-CONFORM	ANCE (NCR)		***************************************	
DATE	OTED	Description of NC			ion B	Verifi	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		on C	Chief Eng	QC Inspector
					ļ		•		
	<u> </u>								
									1




W/O:			V	ORK ORDER CHAN	IGES					
DATE	STEP	PRO	CEDURE CH	IANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									Prod Mgr	·
						·				
			,,							
Part No	:	PAR #:	Fault Ca	tegory:	NCI	R: Yes N	lo DQA	!	Date: _	
	R	esolution:	Disposit	ion:	QA	N/C Clo	sed:		Date:	
NCR:		\	WORK OR	DER NON-CONFOR	MANCE	(NCR)	1			
DATE	STEP	Description of NC			Section B		Verifica	tion	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Descriptio Chief Eng	n	Sign & Date	Section		Chief Eng	QC Inspector
										:
										-
	-									



Dart Aerospace

W/O:		WORK ORDER CHANGES								
DATE STEP		PRO	PROCEDURE CHANGE By Da				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		•								
Part No	:	PAR #:	Fault Cate	egory:	NCF	l: Yes N	o DQ	Á:	_ Date: _	
Resolution:			Disposition:		_ QA: N/C Closed: _			Date:		
NCR:		,	WORK ORD	ER NON-CONFORMA	NCE	(NCR)				
DATE	STEP	Description of NC				ction B Verifi			Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Sect	on C	Chief Eng	QC Inspector
										5
						· · · · · · · · · · · · · · · · · · ·				
f	1				1					



	-							•		
W/O:		WORK ORDER CHANGES								
DATE	STEP	PROCEDURE CHANGE				By Date		Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			and the contraction							
			·							
		PAR #:	Fault Cat	egory:	_ NCR:	Yes N	lo DQA		Date:	
		esolution:	n: Disposition:			QA: N/C Closed:			Date:	
NCR:			WORK OR	DER NON-CONFORMA	NCE (NCR)				
DATE	STEP	Description of NC Section A	Corrective Action Section B			——— verifica			Approval	Approval
	SIEP		Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector
									:	
	1									
1										

8 -- 0.75 --- R0.06 TYP 3.00 1.50

who wolety

2

D3913-15 WIDE HANDLE PLATE

1

С

DESIGN DART AEROSPACE LTD DRAWN JAH HAWKESBURY, ONTARIO, CANADA CHECKED DRAWING NO. REV. A D3913 MFG. APPR. SHEET 6 OF 6 APPROVED TITLE DE APPR. DATE 10.03.16

NOTES:

1) MATERIAL: 304/316 STAINLESS STEEL SHEET ANNEALED 2B FINISH,
PER MIL-S-5059 OR AMS 5513/5524 OR ASTM A240 OR ASME SA240
REF DART SPEC M304S11GA

2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX

6) IDENTIFICATION: N/A

7) WEIGHT: 0.31 lbs

5

Dart Aerospace Ltd	Di	art	Aero	spac	e Ltd
--------------------	----	-----	------	------	-------

W/O:	····	WORK ORDER CHANGES							1		
DATE	STEP	PRO	PROCEDURE CHANGE By Date					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
						·					
	:				8-4						
		PAR #:	Fault Ca	tegory:		NC	R: Yes	No DQA :		Date:	
		esolution:	Disposition:				: N/C Cld	osed:	Date:		
NCR:			WORK OR	DER NON	-CONFOR	MANCE	(NCR)			
DATE	STEP	Description of NC Section A				Section B	Verifica			Approval	Approval
DATE			Initial Chief Eng	Actio	on Description Chief Eng	on 	Sign & Date	Section		Chief Eng	QC Inspector
		•									
		•									
ı	.					· .	lii.				
 						1.	<i>[</i> [
											:.
	-									**	
ì					•						
						mC					